

Motor starter TFA2 with shunt release


with electronical unit for 3-phase motors with thermal contacts mounted to the coil.

Application:

The device is for the start-up and protection of a 3-phase motor with integrated thermal contacts. It can be used for motors with rated current up to 25 ampere and a voltage up to 400. The motor starter will not cut-off in case of a power failure.




3 ~ 400 V, 50/60 Hz or regulated voltage



Star-connection

Attention!

Please absolutely see that the thermal contact will be only connected to the clamps marked with TF. In case of non-observance a short-circuit may occur that results in destroying the thermal contact.



Delta-connection

0.0800.0271 05/03